



#ONE BRAND #ONE SOURCE #ONE SYSTEM



CASE STUDY

Superior Wear Protection Lining Solutions

At a major copper mine in South Australia, REMALINE MP 40 CN, a high quality rubber lining with a built-in wear layer, was used for the re-lining of a neutralisation tank.

REMALINE MP 40 CN was chosen due to its strong wear resistant properties and long service life, with the tank's existing REMALINE rubber lining having lasted for over 15 years, resulting in significant cost savings for the client.

Even after 15 years of usage, upon examination once removed the existing lining showed minimal signs of wear, still remaining in good working condition.

Almost 200 square metres of REMALINE MP 40 CN was used for the re-lining of the tank, with our teams working around the clock to ensure it was back up and running as soon as possible for the client.



7 days

Efficient installation in just seven days



200m²

Over 200m² of REMALINE rubber lining used



15 years

Previously lined with REMALINE for over 15 years