

Rubber lining that lasts



REMA LINE35: Rubber lining that outlasts the competition

A gold and silver mine in North Queensland was experiencing wear issues with their existing rubber lining across key equipment, including: chutes, spools and a cyclone overflow hopper.

The existing lining delivered a service life of approximately 18 months before requiring replacement, creating ongoing maintenance demands and downtime considerations for the site.

The customer required a more durable lining solution that could:

- Transport coarse slurry with minimal wear
- Extend wear life in high-abrasion areas
- Reduce maintenance frequency
- Maintain reliable availability with minimal lead time

A trial was conducted using REMALine MP 35 in 6mm thickness as a replacement lining material.



